

II

1516(T)/25 NORTH SEA - Netherlands Sector - Fairway. Buoyage. Depths.

Source: Netherlands Notice 11/70(T)/25

1. Within the Slijkgat fairway, the water depth is reduced.
2. Shoaling has been reported between buoy *SG-6*, in position $51^{\circ} 51' \cdot 14N.$, $3^{\circ} 55' \cdot 06E.$ and buoy *SG-8*, in position $51^{\circ} 50' \cdot 79N.$, $3^{\circ} 55' \cdot 68E.$ as follows:

Depth

3·7m

2·7m

Location

Mid fairway

In line with the red buoyage

3. A shoal depth, 2·7m, has been reported in line with the green buoyage at buoy *SG-15*, in position $51^{\circ} 51' \cdot 22N.$, $3^{\circ} 59' \cdot 73E.$
4. Mariners are advised to keep mid fairway between these positions and navigate with caution in the area.
(WGS84 DATUM)

Chart affected - 110 (INT 1473)