

# ADMIRALTY NOTICES TO MARINERS

## 1736(P)/2020 ENGLAND - East Coast - Buoy.

Source: Port of London Authority  
(SEP: 2020000053142 - 216332).

1. A mooring buoy has been established, in position 51° 26' 749N., 0° 22' 047E.
2. Mariners are advised to navigate with caution in the area.
3. Charts 1186 and 2151 will be updated by NM following New Editions to be published 26 March 2020.  
(ETRS89 DATUM)

Charts affected - 1186 - 2151

## ~~1709(T)/2020 GERMANY - North Sea Coast - Buoy. Fog signal.~~

~~Source: German Notice 9/103(T)/20  
(SEP: 2020000052755 - 216229).~~

- ~~1. The light-buoy, Iso.8s17M, German Bight (GB), Horn Mo(R)30s Ref, in position 54° 10' 78N., 7° 27' 52E. has been withdrawn.~~
- ~~2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)~~

~~Charts affected - 2182A (INT 1043) - 2182B (INT 1042) - 4140 (INT 140) - DE 50 (INT 1045) - DE 87 (INT 1413) - DE 103 (INT 1412)~~

## ~~1713(P)/2020 NETHERLANDS - Restricted area.~~

~~Source: Netherlands Notice 10/90/20  
(SEP: 2020000059051 - 215912).~~

~~1.~~

<i>Update</i>	<i>Feature</i>	<i>Position</i>
Delete	limit of restricted area, entry prohibited, peeked line, and associated entry prohibited symbol, joining:	52° 23' 70N., 4° 53' 82E.
		<del>52° 23' 69N., 4° 53' 76E.</del>
		<del>52° 23' 55N., 4° 53' 79E.</del>
		<del>52° 23' 56N., 4° 53' 86E.</del>

~~Chart affected - 8230~~

## ~~1721(T)/2020 ISRAEL - Mediterranean Sea Coast - Buoy.~~

~~Source: Israeli Notice 31/20  
(SEP: 2020000053130 - 216200).~~

- ~~1. The isolated danger light buoy, Fl(2)8s, in position 32° 51' 68N., 35° 00' 86E. is reported off station.~~
- ~~2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)~~

~~Chart affected - 1585 (INT 3680)~~