

## II

### **5226(T)/21      ENGLAND - South Coast - Buoy.**

Source: Port of Dover Notice 51/21

1. The starboard-hand lateral light-buoy, *Fl.G.2s*, in position  $51^{\circ} 07' \cdot 171\text{N.}$ ,  $1^{\circ} 19' \cdot 350\text{E.}$  is reported off station.
2. Mariners are advised to navigate with caution in the area.  
(ETRS89 DATUM)

**Charts affected - 1698 (INT 1736) - 5605\_14**