

## II

### **795(T)/24      ENGLAND - South Coast - Buoy.**

Source: Dover Harbour Board

1. The yellow light-buoy, *Fl(5)Y.20s*, in position 51° 07'·355N., 1° 20'·684E. is reported to be temporarily extinguished.
2. Mariners are advised to navigate with caution in the area.
3. \*Former Notice 598(T)/24 is cancelled.

\*Indicates new or revised entry  
(ETRS89 DATUM)

**Charts affected - 1698 (INT 1736) - 5605\_14**