II

893(T)/24 ENGLAND - East Coast - Buoy.

Source: Ministry of Defence

- 1. The unlit buoy, DZ No 2, in position 52° 54′-42N., 0° 07′-48E., is reported missing.
- 2. Mariners are advised to navigate with caution in the area. (ETRS89 DATUM)

Charts affected - 1200 (INT 1556) - 5614_11 - 5614_12