## 3598(P)/23 ENGLAND - East Coast - Works. Channel limits.

Source: Harwich Haven Authority

- 1. Works to deepen the Harwich Deep Water Channel to 16.0m have been completed.
- 2. There have also been changes to the limits of Harwich Deep Water Channel. The most significant changes are as follows:

 New Position
 Former Position

 51° 52′·24N., 1° 33′·20E.
 51° 52′·24N., 1° 33′·14E.

 51° 55′·413N., 1° 18′·954E.
 51° 55′·397N., 1° 18′·937E.

 51° 55′·720N., 1° 18′·560E.
 51° 55′·715N., 1° 18′·538E.

- 3. For the latest information consult Harwich Harbour Operations Service (or Harwich VTS) and local notices.
- 4. These changes will be included in the next New Edition of Charts 1491, 2693, 2052, 5607\_4, 5607\_5, 5607\_6, to be published late 2023.
- 5. Chart 1183, 1610, 2692 and 5607\_2 will be updated by Notice to Mariners.
- Mariners are advised to navigate with caution in the area. (WGS84 DATUM)

Charts affected - 1183 (INT 1561) - 1491 (INT 1580) - 1610 (INT 1511) - 2052 (INT 1560) - 2692 - 2693 (INT 1570) -  $5607\_2$  -  $5607\_4$  -  $5607\_5$  -  $5607\_6$